Tel.: 05203/9719-0 Fax.: 05203/9719-40

- Certificate / Product Information -

RAVENOL Scheibenfrostschutz Konzentrat

Art. 1420100

Description:

RAVENOL Scheibenfrostschutz Konzentrat is a winter screenwash antifreeze concentrate with a special pleasant citrus perfume, based on alcohols.

RAVENOL Scheibenfrostschutz Konzentrat for the windscreen washing installation protects against icing, keeps the windscreen free of ice, is environment-friendly, cleans intensively and offers a clear sight in traffic during the winter months.

Application Directions:

RAVENOL Scheibenfrostschutz Konzentrat is mixed with water according to the following mixing table. Make sure the water and concentrate are well mixed. After filling with the windscreen antifreeze, operate the windscreen washing installation so that the lines up to the spray nozzle are free of water.

Concentrate Substance	Water	Freeze protection to approx.	
2 parts	1 part	-30°C	
1 part	1 part	-20°C	
1 part	2 parts	-10°C	

Technical Characteristics:

RAVENOL Scheibenfrostschutz Konzentrat offers:

- A very good cleaning performance
- Material compatibility
- antifreeze without dilution has a freeze protection to -60°C
- Suitable for polycarbonate windscreens
- Lacquer compatibility
- Suitability for use in fan jets
- · Compatible for wipers, plastics and polymers
- Free of methanol

Technical Values:

Characteristics	Unit	Data	Test according to
Colour		blue	visual
Odour		citrus	smell
Density at 20°C	kg/m³	923,0	EN ISO 12185
Flash point (Closed Cup)	°C	> 21,0	DIN EN ISO 13736
Freezing Point (mixture 2:1)	°C	-30	ASTM D1177
Freezing Point (mixture 1:1)	°C	-20	ASTM D1177
Freezing Point (mixture 1:2)	°C	-10	ASTM D1177

All indicated data are approximate values and are subject to the commercial fluctuations.

09.06.21 Page 1 from 1

To the best of our knowledge all information reflects the current state of findings and our development. Subject to change. Any reference to DIN standards are solely for product description purposes and do not represent a guarantee. If problems occur please consult a technician.